

New Product	Product Update	Product Information
Technical Information	Price Update	Marketing Information
No. 2015/13	Date May 28, 2015	Page 1/2

PowerView3 – HMI Module Software Release 1.0.6



As of now all PowerView3 modules are delivered by MOTORTECH with software version 1.0.6.

To update a PowerView3, read chapter Software Update in the latest version of the Operating Manual, which can be downloaded at www.motortech.de. When updating the software, notice the Board Support Package (BSP) version, which is displayed in the view Display Information of your PowerView3.

If a software version lower than 0.14.0 is installed on your PowerView3, first carry out the update backup, which can be found in the accordingly named sub directory. This update installs a mechanism that makes sure that during all future updates the prior software version can be restored. The file About.txt in the directory Update-Backup contains additional information. The software version of your PowerView3 is also shown in the view Display Information.

The new PowerView3 Software, the latest Operating Manual as well as the update backup can be downloaded at the following link (approx. 20 MB):

<http://www.motortech.biz/downloads/MOTORTECH-SoftwarePackage-PowerView3-FW-1-0-6.zip>

Release 1.0.6 – 2015/02/02 – New Functions and Modifications

- A) 1.0.6 – General
 - -
- B) 1.0.6 – MIC3/4/5
 - Bugfix: Assignment of cylinder names during the recording of runtime data has been corrected.
- C) 1.0.6 – DetCon2/20
 - -

Release 1.0.5 – 2015/02/02 – New Functions and Modifications

- A) 1.0.5 – General
 - -
- B) 1.0.5 – MIC3/4/5
 - Bugfix: Assignment of cylinder names has been corrected.
- C) 1.0.5 – DetCon2/20
 - -

DISTRIBUTION

Customers / others	Yes
Representatives and sales partners	Yes
OEM partners	Yes
MOTORTECH subsidiaries	Yes

New Product	Product Update	Product Information
Technical Information	Price Update	Marketing Information
No. 2015/13	Date May 28, 2015	Page 2/2

Release 1.0.4 – 2014/10/07 – New Functions and Modifications

- A) 1.0.4 – General
 - Bugfix: Small errors that were responsible for occasional crashes of the software have been fixed.
- B) 1.0.4 – MIC3/4/5
 - Bugfix: Window for the trend of the firing angle has been corrected.
 - Bugfix: A problem with the MIC configuration that led to difficulties during startup has been solved.
- C) 1.0.4 – DetCon2/20
 - -

Release 1.0.3 – 2014/08/04 – New Functions and Modifications

- A) 1.0.3 – General
 - Bugfix: A problem in the device configuration has been solved.
 - Bugfix: A problem with the time zones has been solved.
- B) 1.0.3 – MIC3/4/5
 - -
- C) 1.0.3 – DetCon2/20
 - Bugfix: A problem with the handling of the date and the hardware clock in BSP-1.41.0 has been solved.

Release 1.0.2 – 2014/07/31 – New Functions and Modifications

- A) 1.0.2 – General
 - Bugfix: A problem with the device configuration that could cause occasional crashes when the node ID was changed has been solved.
- B) 1.0.2 – MIC3/4/5
 - -
- C) 1.0.2 – DetCon2/20
 - -

Release 1.0.1 – 2014/07/29 – New Functions and Modifications

- A) 1.0.1 – General
 - -
- B) 1.0.1 – MIC3/4/5
 - Bugfix: A problem with the recording of runtime data has been solved.
- C) 1.0.1 – DetCon2/20
 - Bugfix: A problem with the recording of runtime data has been solved.

DISTRIBUTION

Customers / others	Yes
Representatives and sales partners	Yes
OEM partners	Yes
MOTORTECH subsidiaries	Yes