


New Product	Product Update	Product Information
Technical Information	Price Update	Marketing Information
No. 2015/10	Date April 23, 2015	Page 1/1

Repair Kits for Conventional Shielded Primary Leads

Repair kits consist of the 90 or 180 degree connector and the 2 pole wire attached to it. The flexible conduit with adapters needs to be reused.



Ordering Information

Ignition Coil Connector	P/N	Lead Length	Equivalent to	For use with Primary Lead Length 10" – 180"
180° 3 pole, Socket	95.01.010-42-RC	42"	583017-42	95.01.010-L, 593022-L
	95.01.010-60-RC	60"	583017-60	95.01.010-L, 593022-L
	95.01.010-96-RC	96"	583017-96	95.01.010-L, 593022-L
	95.01.010-180-RC	180"	583017-180	95.01.010-L, 593022-L
90° 3 pole, Socket	95.01.020-42-RC	42"	583018-42	95.01.020-L, 593027-L
	95.01.020-60-RC	60"	583018-60	95.01.020-L, 593027-L
	95.01.020-96-RC	96"	583018-96	95.01.020-L, 593027-L
	95.01.020-180-RC	180"	583018-180	95.01.020-L, 593027-L

DISTRIBUTION

Customers / others	Yes
Representatives and sales partners	Yes
OEM partners	Yes
MOTORTECH subsidiaries	Yes